



- (5) Using the locator pins to correctly locate, install steel support to post assembly with (2) #6 x 1-5/8" deck screws in bottom holes and (1) #10 x 1-1/2" span head screw in top hole. Note: Ensure that the screws are tight before continuing assembly.
- (6) Place and locate the post crossarm over the steel support and to post assembly. Secure with (2) #6 x 1-5/8" deck screws.
- (7) Install the mounting plate to the post crossarm with (4) #10-24 x 1" hex head screws.

- 
- GIBRALTAR**
INDUSTRIES
TAYLORSVILLE, MS
39168



SOLAR GROUP
A GIBALTAR COMPANY